



Bimetal measuring instruments

with slave pointer
(maximum current ammeter)

Type:
NM / MQ .. DIN

Square cut-out
Class 3
Energy consumption 1,9 VA for 5 A,
0,9 VA for 1 A
Setting time 8 min., 15 min. on request
Reset button sealable

plastic housing

metal housing



Type	NM 48	NM 72	NM 96	MQ 72 DIN	MQ 96 DIN	MQ 144 DIN
Front frame (mm)	48 x 48	72 x 72	96 x 96	72 x 72	96 x 96	144 x 144
Cut-out (mm)	45 x 45	68 x 68	92 x 92	68 x 68	92 x 92	138 x 138
Scale length (mm)	44	62	90	62	90	130
Weight (kg)	0,10	0,12	0,17	0,20	0,25	0,75



Types and variants

for use with current transformer						
sec. 5 A						
sec. 1 A	X	X	X	X	X	X



Bimetal measuring instruments

with slave pointer, combined with
moving-iron ammeter
(maximum and instantaneous current
ammeter)

Type:
NMW / MWQ .. DIN

Square cut-out
Class 3 (bimetal) / class 1,5 (moving iron)
Energy consumption 2,5 VA for 5 A,
1,5 VA for 1 A
Setting time 8 min., 15 min. on request
Reset button sealable

plastic housing

metal housing



Type	NMW 72	NMW 96	MWQ 72 DIN	MWQ 96 DIN	MWQ 144 DIN
Front frame (mm)	72 x 72	96 x 96	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	68 x 68	92 x 92	138 x 138
Scale length (mm)	62 / 43	90 / 70	50 / 46	95 / 74	135 / 100
Weight (kg)	0,16	0,25	0,34	0,42	0,90



Types and variants

for use with current transformer					
sec. 5 A					
sec. 1 A	X	X	X	X	X