



# PANEL METERS ANALOG N + DIN-SERIES WAS/PAS FOR TOP HAT RAILS

**TECHNICAL INFORMATION** 




# Panel meters analog

General description, dimensions, scale designs and variants		Page 4
General special versions		Page 11
Moving-iron measuring instruments		
Description		Page 12
Special versions		Page 12
Alternating current and alternating voltage	NW, WQ DIN	Page 14
Voltmeters for three-phase current power systems with selector switch	NW SU	Page 15
Moving-coil measuring instruments		
Description		Page 17
Special versions		Page 17
Direct current and direct voltage	NP, PQ DIN	Page 18
Direct current and direct voltage 240° scale	PK	Page 20
Direct current and direct voltage slim profile	Р	Page 22
Alternating current and alternating voltage with rectifier	NPG, PGQ DIN	Page 24
Alternating current and alternating voltage with rectifier	DIVE DE	Da 25
240°-scale and slim profile	PKG, PG	Page 25
Bimetal measuring instruments		
Description		Page 26
Alternating current with slave pointer (maximum current ammeter)	NM, MQ	Page 27
Alternating current with slave pointer (maximum current ammeter)		_
combined with moving-iron ammeter (instantaneous current ammeter)	NMW, MWQ	Page 27
Limit controllers		
Description		Page 28
Technical data, special versions		Page 29
Alternating current and alternating voltage	WQ Min / Max	Page 30
Direct current	PQ Min / Max	Page 31
Direct voltage	PQ Min / Max	Page 32
Power meters		
Description		Page 33
Overview analog power meters		Page 34
Active power meters	DWQ DIN	Page 35
Reactive power meters	DWQB DIN	Page 35
Power factor meters		
Description		Page 37
Alternating and three-phase current of same load	LWQ DIN	Page 38
Frequency meters		
Description		Page 40
Vibrating reed frequency meters	F DIN	Page 41
Pointer frequency meters	FZQ DIN	Page 41
Other measuring instruments		
Operating hour counters for alternating and direct current	SZ DIN, SZ Gs DIN	Page 42
Phase sequence indicators	NDR	Page 43
Fault annunciators with LED display	SM8 / SM16	Page 44
. ,		

#### **General description**

#### Housing


Dimensions	For all types the housing dimensions and the required panel cut-outs comply with DIN 43 700.					
Material	N-Series 48 DIN, PK 72 DIN, PK 96 DIN 72 DIN, 96 DIN, 144 DIN	Lexan 500 (self extinguishing acc. to UL 94 V-0) PC / ABS Sheet steel galvanzizted				
IP code	All housing follow DIN EN 60 529 or special moduls with IP 54 if po	and comply with IP 52 on front side assible				
Snap-on fastening	For types of N-series and 48 DIN no seperat fastening element rec	for panel thickness 1 mm to 3 mm quired				




Fastening acc. to DIN 43 835

with screw clamp

panel thickness 1 mm to 4 mm (standard type, figure 1) with DIN screw clamp shape B, panel thickness 1 mm to 40 mm for types 72 DIN, 96 DIN, 144 DIN (figure 2) against surcharge



#### Contact protection sleeves



#### Technical data


Panel meters analog N+DIN-series


Front panel	Dimensions acc. to DIN 43 718. The front frames are delivered as slim frame (black) for all types.
Scale, pointer	Design acc. to DIN 43 802. The scale graduation is designed as rough/fine division, the pointers as bar pointers.
Zero point setting	All analog measuring instruments offers a zero correction
Accuracy	Acc. to DIN EN 60 051. It is defined under reference conditions, referred to the full scale. With zero point offset, the sum of both full scale values applies. In case of power factor measuring instruments and resistance meters (scale characteristics highly nonlinear), the measuring error is referred to the scale length.
Reference conditions	Temperature $20^{\circ}\text{C} \pm 2\text{K}$ , nominal operating position $\pm 1^{\circ}$
Influecing quantities	Operating position normally vertical $\pm$ 5°, in case of deviating operating position, the angle of the horizontal position must be specified. Temperature influence, unless specified otherwise, is the additional error $\leq$ 1,5 % at 20 °C $\pm$ 10 K environmental temperature. Ferromagnetic control panels have no influence on the measuring accuracy.
Operating temperature	The measurement instruments operate faultlessly within a temperature range of –25°C bis +55°C (unless specified otherwise).
Mechanical strength	The measuring elements are designed with a steel tip bearing. Their mobile element is supported in spring-loaded ceramic stones. This guarantees a vibration resistance of up to 2.5 g and an impact resistance of up to 15. For higher levels of stress and loads, carbide tips are used.
EMC	EMC according to DIN EN 61 326
Safety regulations	According to DIN EN 61 010 part 1. Protection class acc. to DIN EN 60 529, connecting terminals with protection against contacts, back-of-hand-proof, IP10.

Types	Measuring category	Working voltage phase to neutral AC effective or DC	Test voltage/ Conditions
For all N types, WQ 48 DIN, PQ 48 DIN, WAS 45, SZAS 45 (Plastic housing)		300 V	4 kV
For all PQ, WQ, MQ, DWQ, LWQ, F, SZ, MWQ72, MWQ96 (Metal housing)		300 V	2,5 kV installed in grounded metal panel
Round scale indicator 240° of Pk typ Narrow profile of the device types P 48 x 24, P 72 x 24, P 96 x 24, P 144 x 36 (Plastic housing)	CAT III	150 V	2,5 kV
MWQ144 (Metal housing)		150 V	2,5 kV installed in grounded metal panel
PAS 45 (Plastic housing)		100 V	2,5 kV

**Dimensions** 

for panel meters analog, square cut-out







Types			a	b	c
NW, NP, NPG, NMW	72	-15 A	72	58	5
		> 15 - 60 A	72	64	5
NW, NP, NPG, NMW	96	-15 A	96	58	5
		> 15 - 60 A	96	64	5
WQ, PQ, PGQ	48 DIN	-15 A	48	47	5
		> 15 - 60 A	48	53	5
WQ, PQ, MQ, Fz, SZ, LWQ	72 DIN	-15 A	72	60	5
Fz, SZ, LWQ		> 15 - 60 A	72	66	5
WQ, PQ, MQ, LWQ, Fz, DWQ, SZ	96 DIN	-15 A	96	60	5
Fz, DWQ, SZ		> 15 - 60 A	96	66	5
WQ, PQ, MQ	144 DIN	-15 A	144	61	7
Fz		> 15 - 60 A	144	66	7
PK, PKG	48 DIN	- 15 A	48	68	5
		> 15 - 60 A	48	73	5
PK, PKG	72 DIN	- 15 A	72	54	5
		> 15 - 60 A	72	54	5
PK, PKG	96 DIN	- 15 A	96	54	5
		> 15 - 60 A	96	54	5
PK, PKG	144 DIN	- 15 A	144	69	7
		> 15 - 60 A	144	75	7
MWQ	72 DIN	/ 5 A	72	102	5
MWQ	96 DIN	/ 5 A	96	102	5
MWQ	144 DIN	/ 5 A	144	99	7
SM 8 / SM 16	96 DIN		96	56	5

# **Dimensions**


for panel meters analog, rectangular cut-out







a	b	c	d	Durchbruch
48	24	70	18	45 x 22
72	24	86	18	68 x 22
72	36	105	32	68 x 34
96	24	102	18	92 x 22
96	48	126	42	92 x 46
144	36	202	32	138 x 33
144	72	168	68	138 x 69
	48 72 72 96 96 144	48 24 72 24 72 36 96 24 96 48 144 36	48     24     70       72     24     86       72     36     105       96     24     102       96     48     126       144     36     202	48     24     70     18       72     24     86     18       72     36     105     32       96     24     102     18       96     48     126     42       144     36     202     32


# Scale graduation in original size





8


























10

Notice	

9

### General special versions

Increased requirements	Shakeproof > 2,5 g up to 5 g from 100 μA and 100 mV					
	Acid-resistant and splash proof					
	IP 54, front side	<ul><li>Types 72 DIN and 96 DIN</li></ul>				
	(with screw fixing only	N-Series				
	conditionally tropicalized					
Pointer	Red marker pointer, ad	Red marker pointer, adjustable at front side, for sizes 72, 96, 144 only				
Scales	Imprint	red marking at arbitray position of scale				
		colored sector at arbitray position of scale				
		e.g. charge / discharge				
		second scale numbering				
	Double scale					
	Special calibration	according to curve or table				
		in different measuring unit, e.g. min-1, bar, m/s				
	Special scale	blanc scale (without scale graduation and measuring unit)				
		scale black, pointer, graduation and numbering white or yellow				
		(as far as possible)				
		scale fine graduation				
	Illumination	by means of 12 V or 24 V lamp plugged at rear side				
	_	(as far as possible)				
Fastening	screw clamp shape B a	cc. to DIN 43 835				
Front frame	grey (similar to RAL 7037, as far as possible)					
Front glass	low-glare glass					
	plexiglas					
Cover frame	with glass pane acc. to	DIN 43 718 for cut-outs acc. to DIN 43 700				
	68 mm x 68 mm					
	92 mm x 92 mm					
	138 mm x 138 mm					
Blind cover	from black plastic mate	erial for cut-outs acc. to DIN 43 700				
	45 mm x 45 mm (front	48 mm x 48 mm)				
	68 mm x 68 mm (front	72 mm x 72 mm)				
	92 mm x 92 mm (front	96 mm x 96 mm)				
	92 mm x 22 mm (front	96 mm x 24 mm)				
	92 mm x 45 mm (front	96 mm x 48 mm)				
Protection cover	IP 65 protection for fro					
	IP 65 protection for fro					
Test report	up to 10 test points (de	epending on type)				

#### Moving-iron measuring instruments

#### Application

Moving-iron measuring instruments are mainly used in heavy-current installation for the measurement of alternating currents and alternating voltages (direct measurement or via current or voltage transformer). Moving-iron measuring instruments also indicate the rms value in case of non-sinusoidal quantities within a frequency range of 15-100 Hz.

With direct current and direct voltage, additional indication errors of approx. 1 % may occur due to magnetization errors inside the iron. As compared to moving-coil measuring instruments, the energy consumption is relatively high ranging between 0.6 VA and 2 VA. They are thus not suited for measuring small currents or voltages, like e.g. at shunts, speed sensor, thermoelements, measuring transducers.

#### Measuring systems

- Robust and electrically resistant to high overloads
- Spring loaded toe bearing in ceramic stones
- Damping through silicone bearings, setting time approx. 1 s

for voltmeters

High torque

Damping

Shielding against external magnetic fields

#### Design

Moving-iron measuring instruments are manufactured according to DIN 60 051 as well as according to the other relevant VDE and DIN regulations. The accuracy amounts to 1.5 % referred to the full scale. The graduation of the scale of standard ammeters disposes of a 2-fold overload scale and starts at approx. 10% (20% for voltmeters) of the full scale.

Moving-iron measuring elements are resistant to a permanent 1.2-fold overload, ammeters temporarily to a max. 50-fold overload, voltmeters to a max. 2-fold overload; for the rest, DIN EN 60 051 applies. Voltmeters and ammeters up to 5 A are provided with a shielding against external magnetic fields up to a strength of 4 kA/m, ammeters of 6 A up to 60 A offer a shielding up to a strength of (2 kA/m).

The connection is realized using M4 screws for voltmeters and for ammeters up to 15 A max. 6 mm<sup>2</sup>, M5 screws up to 60 A max. 16 mm<sup>2</sup> (back-of-hand-proof).


#### **Special versions**

Measuring ranges	without overload range	
	outside of standard series	
	increased overload range for CT connection max. 6-fold,	44
	with direct measurement < 50 A max. 5-fold	96, 144
	extended intial range up to 30 % of full scale	72.
	in center of scale (up to 25 A and 800 V) without overload	arößen 72
	extended accuracy1 %	Grö
Special calibration	for direct current	
	for frequency 16 2/3 Hz	
	fixed value between 100 Hz and 400 Hz	
	• for ammeters	
	• for voltmeters	
	fixed value between 400 Hz and 1000 Hz	
	• for ammeters	

increased damping, strong aperiodic, setting time approx. 3 s

#### External magnetic field influence in case of moving-iron measuring instruments


Influence of external magnetic field of a busbar at a horizontal distance of 100 mm and a vertical distance of 150 mm to the moving-iron ammeter.



Due to the capsuled measuring systems, Müller+Ziegler instruments still lie within the required accuracy class even in case of high external magnetic fields.

#### Operating position

In general, the operating position is indicated by a position symbol. For instruments without a position symbol, the reference area is any operating position between horizontal and vertical. The nominal operating position is 1  $^{\circ}$  in each direction from the reference operating position, whereby the influencing effect (in addition to the display error) must not be greater than 50% of the corresponding class error.



14



# Moving-iron measuring instruments

for alternating current and alternating voltage

Type:

NW/WQ..DIN

Square cut-out 40 - 100 Hz, class 1,5	plastic	housing	plastic housing		metal housing	I
Ammeter with 2-fold overload scale Energy consumption: Voltmeter 2 VA Ammeter 0,6-2 VA						
Туре	NW 72	NW 96	WQ 48 DIN	WQ 72 DIN	WQ 96 DIN	<b>WQ 144 DIN</b>
Front frame (mm)	72x72	96x96	48 x 48	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	45 x 45	68 x 68	92 x 92	138 x 138
Scale length (mm)	62	90	42	62	90	130
Weight (kg)	0,20	0,25	0,10	0,26	0,30	0,70

Types and val	riants						
Measuring ranges Alternating voltage							
V	10 15 25 40 60	Х	Х	- - X	X	X	X
	100 150 250 400 500 600	Х	Х	X	X	Х	X
for use with voltage transformer	sec. 100 V sec. 110 V	Х	Х	х	Х	Х	Х
Alternating current							
mA	40 60	Х	Х	<del>-</del> -	Х	Х	Х
	100 150 250 400 600	Х	х	Х	Х	х	Х
A	1 1,5 2,5 4 6 10	х	х	x	х	х	Х
	25 40 60	Х	Х	- - -	Х	Х	Х
for use with current transformer	sec. 5A sec. 1 A	Х	Х	Х	Х	Х	Х

2

 $\infty$ 





# Moving-iron measuring instruments

with integrated selector switch for measurement of the alternating voltage in 3-phase power systems phase against phase as well as phase against neutral with 6 switching positions

Type: **NW** .. **SU** 

Square cut-out 40 - 100 Hz, class 1,5 Energy consumption max. 4 VA

plastic housing






Туре	NW 72 SU	NW 96 SU
Front frame (mm)	72x72	96x96
Cut-out (mm)	68 x 68	92 x 92
Scale length (mm)	62	90
Weight (kg)	0,20	0,25

€

Measuring ranges		
500 V	Χ	X



Measuring transducers	
Mains and limit monitoring	
3 Energy meters	
4 Panel meters digital	
Panel meters analog N+DIN-series	
Meas, instruments for to top hat rail mounting	
7 Universal measuring instruments	
S Current transformers	

Notice	

10 Test 9 Shunts

16

#### Description moving-coil panel meters

#### Application

Moving-coil measuring instruments serve for measuring direct current and direct voltage. For extending the measuring range, shunts, series resistors or voltage dividers are used. The energy consumption of moving-coil measuring instruments is very low; they may thus be connected to shunts, speed sensors, thermocouples, measuring transducers or similar.

Moving-coil measuring instruments with rectifier serve for measuring alternating current and alternating voltage. They measure the arithmetic mean value, but are designed in a way to indicate the rms value in case of sinusoidal variables.

In case of non-sinusoidal variables, an rms-value rectifier is provided. It is able to still process crest factors of max. 8 without problem. The max. error amounts to less than 1% in this case.

#### **Measuring systems**

- Core-magnet measuring system
- Spring loaded toe bearing in ceramic stones

Panel meters analog N+DIN-series - Moving-coil version

- High damping
- Independent of external fields
- Linear scale characteristics

#### Design

Moving-coil measuring instruments are manufactured according to DIN 60 051 as well as according to the other relevant VDE and DIN regulations. The accuracy amounts to 1.5 % referred to the full scale.

The energy consumption lies between 5  $\mu$ W and 50  $\mu$ W, the smallest possible measuring ranges lie around 25 µA and 10 mV. In case of smaller values than stated above, a measuring amplifier is

When adjusting moving-coil measuring instruments for their connection to shunts, an input lead resistance of  $0.06 \Omega$  is principally accounted for; this corresponds to an input lead of 1.3 m, 2 x

Moving-coil measuring instruments are resistant to a permanent 1.2-fold overload, ammeters temporarily to a max. 10-fold overload voltmeters to a max. 2-fold overload; for the rest, DIN EN 60 051 applies.

The connection is made using M4 screws for voltmeters and for ammeters up to 15 A max. 6 mm<sup>2</sup> M5 screws up to 60 A max. 16 mm<sup>2</sup> (back-of-hand-proof), with slim profile moving-coil measuring instruments via blade terminal.

#### General special designs

**Averager** 

Measuring range	Outside of standard series					
	Second measuring range					
	for voltmeters and ammeters up to 15 A with additional numbering					
	with additional graduation and numbering					
	Electrical suppressed initial range starting from 10 V, max. 60 % of full scale					
	Extended intial range, up to 10 % of full screen in center scale					
	Zero point at any position of scale					
	Extended accuracy 1 %					
	Extended accuracy 0,5 % in case of direct current or direct voltage					
	for sizes 96 and 144 only					
Special adjustment	With ammeters $\Delta$ U $\pm$ 1 %					
	With voltmeters Ri ± 1 %					
	Input lead when connected to shunt different to 0,06 $\Omega$					
	Installed potentiometer for voltmeters starting from 60 mV					
	<ul><li>setting rang ± 10 % of full scale</li></ul>					
	● setting range ± 20 % to ± 50 % of full scale					
Increased input	ca. 2000 Ω / V					
resistance	ca. 4000 Ω / V					
	ca. $10000\Omega/V$					
	ca. 20000 $\Omega$ / V (as far as possible)					
$> 20000 \Omega / V$ with measuring amplifier						

e.g. in case of pulse packing controls for measuring ranges from 1 A to 25 A incl. current transformer (for types PQ 72 DIN, PQ 96 DIN and PQ 144 DIN only, basic price



150 200 250

# Moving-coil measuring instruments

for direct current

Type: **NP / PQ .. DIN** 

Square cut-out Class 1,5	plastic housing		plastic housing	metal housing		
Туре	NP 72	NP 96	PQ 48 DIN	PQ 72 DIN	PQ 96 DIN	PQ 144 DIN
Front frame (mm)	72x72	96x96	48 x 48	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	45 x 45	68 x 68	92 x 92	138 x 138
Scale length (mm)	62	90	42	62	90	130
Weight (kg)	0,20	0,25	0,10	0,26	0,30	0,70

Type	s and va	Halits						
Measu	ring ranges							
μΑ	100 150	Ri / Δ U 4400 Ω 2200 Ω	Х	х	X	Х	X	х
	250 400 600	900 Ω 306 Ω 177 Ω	Х	Х	Х	Х	Х	Х
mA	1 1,5 2,5 4 6 10	53 Ω 23 Ω 9 Ω 6,5 Ω 3,5 Ω 2,5 Ω	X	Х	X	X	X	Х
	15 25 40 60	1,3 Ω 60 mV 60 mV 60 mV	х	х	X	X	Х	х
	100 150 250 400 600	60 mV 60 mV 60 mV 60 mV	Х	Х	Х	Х	Х	х
Α	1 1,5 2,5 4 6 10	60 mV 60 mV 60 mV 60 mV 60 mV 60 mV 60 mV	х	х	X -	х	х	х
	25	60 mV	X	X	-	X	X	X
	with shunt							
mV	60 100 150	12 Ω 20 Ω 30 Ω	х	Х	X	Х	X	х
for use		ring transducer						
mA	0-20	2,2 Ω	Х	Х	X	X	X	Х
.,	4-20	50 Ω	X	X X	X	X	X X	X X
V	0-10	10 k Ω	Х	Х	Х	Х	Х	Х

Test Capparatus



# Moving-coil measuring instruments

for direct voltage

Type: **NP / PQ .. DIN** 

Square cut-out Class 1,5	plastic housing	plastic housing	metal housing

NP 72	NP 96	PQ 48 DIN	PQ 72 DIN	PQ 96 DIN	PQ 144 DIN
72x72	96x96	48 x 48	72 x 72	96 x 96	144 x 144
6060	0202	4545	6060	0202	120 - 120

Туре	NP 72	NP 96	PQ 48 DIN	PQ 72 DIN	PQ 96 DIN	PQ 144 DIN
Front frame (mm)	72x72	96x96	48 x 48	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	45 x 45	68 x 68	92 x 92	138 x 138
Scale length (mm)	62	90	42	62	90	130
Weight (kg)	0,20	0,25	0,10	0,26	0,30	0,70

Measu	ring ranges	<b>i</b>						
		Ri / Δ U						
mV	40	200 Ω / V	X	Х	Χ	Χ	Х	X
	60	200 Ω / V	X	Х	X	X	X	X
	100	200 Ω / V						
	150	200 Ω / V						
	250	200 Ω / V	X	Х	X	X	X	X
	400	1000 Ω / V						
	600	1000 Ω / V						
V	1	1000 Ω / V						
	1,5	1000 Ω / V						
	2,5	1000 Ω / V						
	4	1000 Ω / V						
	6	1000 Ω / V						
	10	1000 Ω / V						
	15	1000 Ω / V						
	25	1000 Ω / V	Х	Х	Х	Х	Х	Х
	40	1000 Ω / V	^	^	^	^	^	^
	60	1000 Ω / V						
	100	1000 Ω / V						
	150	1000 Ω / V						
	250	1000 Ω / V						
	400	1000 Ω / V						
	500	1000 Ω / V						
	600	1000 Ω / V						

20



# Moving-coil measuring instruments

for direct current

Type: **PK .. DIN** 





plastic housing



metal housing

Туре	PK 48 DIN	PK 72 DIN	PK 96 DIN	PK 144 DIN
Front frame (mm)	48 x 48	72 x 72	96 x 96	144 x 144
Cut-out (mm)	45 x 45	68 x 68	92 x 92	138 x 138
Scale length (mm)	70	105	150	230
Weight (kg)	0,20	0,30	0,40	0,90

Types and variants

Square cut-out

class 1,5 240° scale

7   00 01 10 1			1	r and a second	i e	ı
Measuring range	es .					
		Ri / ∆ U				
μΑ	100	4400 Ω				
	150	4000 Ω				
	250	2500 Ω	Х	X	Χ	X
	400	2000 Ω				
	600	1400 Ω				
mA	1	300 Ω				
	1,5	250 Ω				
	2,5	120 Ω				
	4	80 Ω				
	6	60 mV	, ,	.,	.,	v
	10	60 mV	Х	Х	Х	Х
	15	60 mV				
	25	60 mV				
	40	60 mV				
	60	60 mV				
	100	60 mV				
	150	60 mV		Х	Х	
	250	60 mV	Х			Х
	400	60 mV				
	600	60 mV				
Α	1	60 mV				
	1,5	60 mV	.,		.,	.,
	2,5	60 mV	X	Х	Х	Х
	4	60 mV				
for use with shunt						
mV	60	12 Ω				
	100	20 Ω	X	Х	Х	Х
	150	30 Ω				
for use with measuring transducer						
mA	0-20	3Ω	X	Х	Χ	X
	4-20	45 Ω	Х	Х	Х	Х
V	0-10	10 k Ω	X	X	Х	Х



# Moving-coil measuring instruments

for direct voltage

Type: **PK .. DIN** 

Square cut-out class 1,5 240° scale









Туре	PK 48 DIN	PK 72 DIN	PK 96 DIN	PK 144 DIN
Front frame (mm)	48 x 48	72 x 72	96 x 96	144 x 144
Cut-out (mm)	45 x 45	68 x 68	92 x 92	138 x 138
Scale length (mm)	70	105	150	230
Weight (kg)	0,20	0,30	0,40	0,90



Measuring rar	nges					
		Ri / ∆ U				
mV	60	200 Ω / V				
	100	200 Ω / V				
	150	200 Ω / V	V	V	v	v
	250	200 Ω / V	Х	Х	Х	Х
	400	1000 Ω / V				
	600	1000 Ω / V				
V	1	1000 Ω / V				
	1,5	1000 Ω / V				
	2,5	1000 Ω / V				
	4	1000 Ω / V				
	6	1000 Ω / V				
	10	1000 Ω / V				
	15	1000 Ω / V				
	25	1000 Ω / V	Х	х	Х	х
	40	1000 Ω / V	^	^	^	^
	60	1000 Ω / V				
	100	1000 Ω / V				
	150	1000 Ω / V				
	250	1000 Ω / V				
	400	1000 Ω / V				
	500	1000 Ω / V				
	600	1000 Ω / V				



# Moving-coil measuring instruments

for direct current

Type:

P ...

Rectangular cut-out class 1,5 Horizontal scale (vertical scale possible - please specify at order) plastic housing

metal housing

Туре	P 48x24	P 72x24	P 72x36	P 96x24	P 96x48	P 144x36	P 144x72
Front frame (mm)	48x24	72x24	72x36	96x24	96x48	144x36	144x72
Cut-out (mm)	45x22	68x22	68x34	92x22	92x46	138x33	138x69
Scale length (mm)	32	52	52	60	60	95	95
Weight (kg)	0,08	0,10	0,12	0,15	0,25	0,50	0,80

Measuri	ing ranges							
μΑ	100 150	Х	Х	Х	Х	Х	Х	Х
	250 400 600	Х	Х	Х	X	Х	Х	Х
mA	1 1,5 2,5 4 6 10	X	X	X	X	X	X	X
	15 25 40 60	X	X	X	Х	X	X	X
	100 150 250 400 600	X	X	X	X	X	X	X
Α	1	Х	Х	Х	X	X	Х	Х
	vith shunt							
mV	60 100 150	Х	Х	Х	Х	Х	Х	Х
	with measuring tra	nsducer						
mA	0-20	Х	Х	Х	Х	Х	Х	Х
	4-20	X	X	X	X	X	X	X
V	0-10	Х	X	X	X	X	X	X

metal housing

() Test apparatus



# Moving-coil measuring instruments

for direct voltage

Type: P ...

ar cut-out

Rectangular cut-out class 1,5 Horizontal scale (vertical scale possible - please specify at order)

Туре	P 48x24	P 72x24	P 72x36	P 96x24	P 96x48	P 144x36	P 144x72
Front frame (mm)	48x24	72x24	72x36	96x24	96x48	144x36	144x72
Cut-out (mm)	45x22	68x22	68x34	92x22	92x46	138x33	138x69
Scale length (mm)	32	52	52	60	60	95	95
Weight (kg)	0,08	0,10	0,12	0,15	0,25	0,50	0,80

plastic housing

Measur	ing ranges							
mV	60	Х	Х	X	X	X	Х	Х
	100							
	150							
	250	Х	Χ	Х	Х	X	X	Х
	400							
	600							
V	1							
	1,5							
	2,5							
	4 6							
	10							
	15							
	25							
	40	Х	Х	Х	Х	Х	X	Х
	60							
	100							
	150							
	250							
	400							
	500							
	600							

lest apparatus

24



# Moving-coil measuring instruments

with rectifier

for alternating current and alternating voltage

# Type: NPG / PGQ .. DIN

Square cut-out 40 - 100 Hz, class 1,5	plastic housing		plastic housing	metal housing		
Туре	NPG 72	NPG 96	PGQ 48 DIN	PGQ 72 DIN	PGQ 96 DIN	PGQ 144 DIN
Front frame (mm)	72x72	96x96	48 x 48	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	45 x 45	68 x 68	92 x 92	138 x 138
Scale length (mm)	62	90	42	62	90	130
Weight (kg)	0,20	0,25	0,10	0,26	0,30	0,60

Types and	i variants						
Measuring rar	nges						
V	10						
	15						
	25						
	40						
	60						
	100	X	X	X	Х	X	X
	150						
	250						
	400						
	500						
	600						
Α	1						
	1,5						
	2,5						
	4	_	_	_	Х	Х	X
	6	_	_	_	^	^	^
	10						
	15						
	25						



# **Moving-coil measuring** instruments

with rectifier

for alternating current and alternating voltage

Type:

PKG..DIN/PG

Square and rectangular cut-outs 40 - 100 Hz, Class 1,5 240° scale and slim profile		olastic housin	g	metal housing	p	lastic housin	g	
Туре	PKG 48 DIN*	PKG 72 DIN	PKG 96 DIN	PKG 144 DIN	PG 48 x 24	PG 72 x 24	PG 96 x 24	
Front frame (mm)	48 x 48	72x72	96x96	144 x 144	48 x 24	72 x 24	96 x 24	
Cut-out (mm)	45 x 45	68 x 68	92 x 92	138 x 138	45 x 22	68 x 22	92 x 22	
Scale length (mm)	70	105	150	230	32	52	60	
Weight (kg)	0.20	0.30	0.40	0.90	0.08	0.10	0.12	



#### Types and variants

Measur	ing ranges								
V	10 15 25 40 60 100 150 250 400 500 600	х	х	х	х	х	х	х	
mA	1 1,5 2,5 4 6 10 15 25 40 60	X -	х	х	х	х	х	х	
	100 150 250 400 600	-	Х	Х	Х	Х	Х	Х	
A	1 1,5 2,5 4 5	-	х	Х	Х	Х	Х	Х	

\* PKG 48 DIN - changes depth of instrument

#### Bimetal measuring instruments

#### **Application**

Bimetal measuring instruments are used for monitoring the load ratios and conditions of electrical distribution installations. Due to their thermal inertia, the displayed measured values equal the rms value of the current; a built-in slave pointer is used to show the maximum values.

#### Measuring systems

- Highly robust
- Ultra high torque
- Trunnion bearing
- Setting time 8 min or 15 min

#### Design

Bimetal measuring instruments are manufactured according to DIN 60 051 as well as according to the other relevant VDE and DIN regulations. The accuracy amounts to 3 % referred to the full scale. The scale graduation starts at approx. 15 % of the full scale and has a 1.2-fold overload scale. Bimetal measuring instruments show the square mean value of the current, the measured value equals the rms value and is independent of the waveform. Due to the extremely high torque, a slave pointer showing the maximum current may be used. Using a sealable reset button, the maximum pointer (slave pointer) may be reset up to the measuring element pointer. Another model combines bimetal measuring elements with moving-iron measuring elements (class 1.5) inside one housing. This allows for measuring maximum value, mean value and instantaneous value of the current on one scale at the same time. The standard type allows for measuring currents within a frequency range of 15 Hz to 100 Hz. Bimetal measuring systems are resistant to a 1.2-fold overload and moving-iron systems to a 2-fold overload, temporarily also up to a 10-fold overload, for the rest DIN EN 60 051 applies. Moving-iron measuring elements are provided with a shielding against external magnetic fields up to a strength of 4 kA/m. The connection is made using M4 screws (back-of-hand-proof).

#### **Measuring ranges**

Bimetal measuring instruments

0-5 / 6 A. If connectect to current transformer sec. 5 A the scale is designed in a way that the full scale is 20 % higher than the primary current of the current transformer,

e.g. current transformer 250 / 5 A, display range 0-300 A.

Moving-iron measuring instruments combined with bimetal measuring instruments

0-5 / 10 A. If connectect to current transformer sec. 5 A the scale is designed in a way that the full scale is 100 % higher than the primary current of the current transformer,

e.g. current transformer 250 / 5 A, display range 0-500 A.

#### **Energy consumption**

Bimetal measuring system 1,9 VA for 5 A, 0,9 VA for 1 A combined with moving-iron measuring system 2,5 VA for 5 A, 1,5 VA for 1 A

#### Special versions

Fixed value between 100 Hz and 1000 Hz

at bimetal measuring instrument

at combined bimetal / moving-iron measuring instrument

Extended initial range up to 30 % of full scale

in center scale (moving-iron measuring element)

**Bimetal measuring instruments** with slave pointer (maximum current ammeter)

Type: NM/MQ..DIN

Square cut-out Class 3

Energy consumption 1,9 VA for 5 A, 0,9 VA for 1 A

Setting time 8 min., 15 min. on request Reset button sealable

plastic housing

metal housing











Туре	NM 48	NM 72	NM 96	MQ 72 DIN	MQ 96 DIN	MQ 144 DIN
Front frame (mm)	48 x 48	72 x 72	96 x 96	72 x 72	96 x 96	144 x 144
Cut-out (mm)	45 x 45	68 x 68	92 x 92	68 x 68	92 x 92	138 x 138
Scale length (mm)	44	62	90	62	90	130
Weight (kg)	0,10	0,12	0,17	0,20	0,25	0,75



#### Types and variants

for use with current transformer	1					
sec. 5 A	V	V	V	V	V	V
sec. 1 A	^	^	^	^	^	^



### **Bimetal measuring instruments**

with slave pointer, combined with moving-iron ammeter (maximum and instantaneous current ammeter)

### Type:

NMW / MWQ .. DIN

Square cut-out Class 3 (bimetal) / class 1,5 (moving iron) Energy consumption 2,5 VA for 5 A, 1,5 VA for 1 A

Setting time 8 min., 15 min. on request Reset button sealable

plastic housing











Type	NMW 72	NMW 96	MWQ 72 DIN	MWQ 96 DIN	MWQ 144 DIN
Front frame (mm)	72 x 72	96 x 96	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	68 x 68	92 x 92	138 x 138
Scale length (mm)	62 / 43	90 / 70	50 / 46	95 / 74	135 / 100
Weight (kg)	0,16	0,25	0,34	0,42	0,90



for use with current transformer					
sec. 5 A	V	V	V	V	V
sec. 1 A	^	^	, X	, X	٨

#### Limit controllers

**Application** 

Limit controllers monitor one or two limit values to be set over the entire scale range. They can be used for electrical measureable values.

**Measuring system** 

- Moving-iron measuring system
- Moving-coil measuring system


**Contact device** 

- Optical sampling through infrared reflected light barrier
- Nonreactive sampling
- Setting range 0-100 % (also in case of two contact marks)
- Setting of limit values at the front side

Design

For limit controllers, the same technical data and special models as for normal indicators apply. They are available in sizes 96 DIN and 144 DIN. The following variables may be measured: Direct current, direct voltage, alternating current, alternating voltage, frequency, in connection with a measuring transducer power, power factor, temperature and all other transformed non-electrical quantities. The sampling of the position of the measuring element pointer is done via a noncontact infrared reflected light barrier. A maximum of two limit values may be monitored. In case of the standard type, the relays are energized and are deenergized if the max. contact mark is exceeded or the limit value drops below the min. contact mark (closed-circuit principle). Electronics, relays and 230 V auxiliary voltage are installed; the maximum mounting depth of the device amounts to 68 mm only. The connection is made via a 12-pin terminal block for cross sections up to 4 mm². The measuring element is connected to hexagon bolts with M4 screws in case of voltmeters and ammeters up to 15 A max. 6 mm², M5 screws up to 60 A max. 16 mm² (back-of-hand-proof).


# Function and connection diagram



# Technical data

	Switching accura	су	$\pm1\%$ of scale lenght, (± 0,9 mm for96 DIN or $\pm1,3$ mm for	144 DIN)
	Hysteresis		$\pm$ 0,5 % of scale length, (± 0,4 mm for96 DIN or $\pm$ 0,6 mm for	r144 DIN)
	Response delay		100 ms after limit value is exceeded	
	Sampling		optical, with reflected light barrier	
	Limit value adjust	tment	at front side via full scale range, using screwdriver	
	Temperature rang	ge	-25 °C to +20 °C to +30 °C to +55 °C	
	Relay contacts		1 changeover contact per limit value, max. 8 A, 250 V A	C, 2000 VA
	Switching state		closed-circuit prinziple, (Relay is deengergized if limit val	ue is exceeded)
	Auxiliary voltage		230 V AC ± 15 %, 45-65 Hz, 2 VA	
	Test voltage		2,5 kV, 50 Hz, 10 s, between measuring input, housing, a	uxiliary
			voltage and relay contacts	
Standards	EMC		DIN EN 61 326,	
	Mechanical stren	gth	DIN EN 61 010 part 1	
	Electrical safety		DIN EN 61 010 part 1, pollution degree 2, measuring cat	egory CAT III,
			for working voltages up to 300 V (phase to neutral)	
	Accuracy, overlac	od	DIN EN 60 051	
	IP code		DIN EN 60 529, housing IP 52, terminals IP 10	
Special versions	Measuring range	Movin	g-iron measuring instruments	Page 132
		Movin	g-coil measuring instruments	Page 137
	Auxiliary voltage	110 V /	AC ± 15 %, 45-65 Hz, 2 V	
		24 V A	C + DC, -15 % to +25 %, 2 W,	
		6-30 V	AC + DC, 2 VA, (EMC DIN EN 61 326 class A)	
		36-265	5 V AC + DC, 2 VA, (EMC DIN EN 61 326 class A)	
	Contacts 2 max c	ontacts	or 2 min contacts	
	Adjustment using		l knob, per contact	
	Relays	Revers	ed switching states (open-circuit principle), per contact	
	Relay contacts		geover contacts (only possible for 1 contact)	
	Relay delay		alue between 1 and 30 s, per contact	
		adjusta	able at rear side of housing 1-30 s, per contact	
Dimonsions				

#### Dimensions



Туре	Cut-out			
		a	b	c
	mm	mm	mm	mm
WQ 96 DIN, PQ 96 DIN, PGQ 96 DIN	92+ <sup>0,8</sup> x 92+ <sup>0,8</sup>	96	70	5
WQ 144 DIN, PQ 144 DIN, PGQ 144 DIN	138+1 x 138+1	144	70	7



### **Limit controllers**

for alternating current and alternating voltage

Type: WQ..DIN

Square cut-out 40-100 Hz, moving-iron measuring system

Ammeter with 2-fold overload scale

Energy consumption ammeter 0,6-2 VA

voltmeter ca. 2 VA

metal housing









Туре	WQ 96 DIN	WQ 96 DIN	<b>WQ 144 DIN</b>	<b>WQ 144 DIN</b>
	Min-contact	Min-contact	Min-contact	Min-contact
	or	and	or	and
	Max-contact	Max-contact	Max-contact	Max-contact
Front frame (mm)	96 x 96	96 x 96	144 x 144	144 x 144
Cut-out (mm)	92 x 92	92 x 92	138 x 138	138 x 138
Scale length (mm)	90	90	130	130
Weight (kg)	0,48	0,48	0,90	0,90

Measuring ranges					
V	6 10 15 25 40 60 100 150 250 400 500 600	Х	Х	Х	х
for use with voltage transformer mA	sec. 100 V 40 60 100 150 250 400 600	х	х	х	х
A	1 1,5 2,5 4 6 10 15 25 40	х	х	х	х
for use with current transformer	sec. 5 A (0,6 VA) sec. 1 A (0,6 VA)	х	х	х	х

apparatus



### **Limit controllers**

for direct current

Type: **PQ .. DIN** 

Square cut-out Class 1,5 Moving-coil measuring system metal housing







Туре	PQ 96 DIN	PQ 96 DIN	PQ 144 DIN	PQ 144 DIN
	Min-contact	Min-contact	Min-contact	Min-contact
	or	and	or	and
	Max-contact	Max-contact	Max-contact	Max-contact
Front frame (mm)	96 x 96	96 x 96	144 x 144	144 x 144
Cut-out (mm)	92 x 92	92 x 92	138 x 138	138 x 138
Scale length (mm)	90	90	130	130
Weight (kg)	0,48	0,48	0,90	0,90

### Types and variants

Measurin	ig ranges					
		Ri / Δ U				
μΑ	100	2575 Ω				
·	150	955 Ω				
	250	420 Ω	Х	Х	Х	Х
	400	167 Ω				
	600	77 Ω				
mA	1	28,6 Ω				
	1,5	14,2 Ω				
	2,5	, 7,6 Ω				
	4	3,8 Ω				
	6	1,9 Ω				
	10	1,4 Ω				
	15	, 1,3 Ω				
	25	60 mV	Х	Х	Х	Х
	40	60 mV				
	60	60 mV				
	100	60 mV				
	150	60 mV				
	250	60 mV				
	400	60 mV				
	600	60 mV				
Α	1	60 mV				
	1,5	60 mV				
	2,5	60 mV				
	4	60 mV				
	6	60 mV	Х	Х	Х	Х
	10	60 mV				
	15	60 mV				
	25	60 mV				
	40	60 mV				
for use wi	ith shunt					
mV	60	12 Ω				
	100	20 Ω	Х	Х	X	Х
	150	30 Ω				
for use wi	ith measuring trans					
mA	0-20	1,2 Ω	Х	Х	Х	Х
	4-20	50 Ω	Х	X	X X	X X X
V	0-10	10 kΩ	Х	Х	Х	Х

Alternating current: with rectifier, type PGQ 96 DIN or PGQ 144 DIN, 40 - 10000 Hz sinusoidal

Measuring ranges between 100 μA and 600 mASurcharge:Measuring ranges between 1 A and 25 ASurcharge:



### **Limit controllers**

for direct voltage

Type: **PQ .. DIN** 

Square cut-out Class 1,5 Moving-coil measuring system metal housing









Туре	PQ 96 DIN	PQ 96 DIN	PQ 144 DIN	PQ 144 DIN
	Min-contact	Min-contact	Min-contact	Min-contact
	or	and	or	and
	Max-contact	Max-contact	Max-contact	Max-contact
Front frame (mm)	96 x 96	96 x 96	144 x 144	144 x 144
Cut-out (mm)	92 x 92	92 x 92	138 x 138	138 x 138
Scale length (mm)	90	90	130	130
Weight (kg)	0,48	0,48	0,90	0,90

Types and variants

Measurin	ng ranges	Internal resistance				
mV	25	200 Ω / V				
	40	200 Ω / V				
	60	200 Ω / V				
	100	200 Ω / V				
	150	200 Ω / V	X	Х	X	Х
	250	200 Ω / V				
	400	1000 Ω / V				
	600	1000 Ω / V				
V	1	1000 Ω / V				
	1,5	1000 Ω / V				
	2,5	1000 Ω / V				
	4	1000 Ω / V				
	6	1000 Ω / V				
	10	1000 Ω / V				
	15	1000 Ω / V				
	25	1000 Ω / V	Х	х	Х	Х
	40	1000 Ω / V	^	^	^	^
	60	1000 Ω / V				
	100	1000 Ω / V				
	150	1000 Ω / V				
	250	1000 Ω / V				
	400	1000 Ω / V				
	500	1000 Ω / V				
	600	1000 Ω / V				
Alternation	Alternating voltage: with rectifier, type PGQ 96 DIN or PGQ 144 DIN, 40 - 10000 Hz sinusoidal					

Measuring ranges between 25 mV and 600 V

Surcharge:

#### **Power meters**

#### Application

Power meters are used for measuring active and reactive power in case of alternating current and threephase current or the active power for direct current. Sinusoidal and non-sinusoidal quantities may be measured. The frequency range amounts to 40-100 Hz, in case of special types 40-400 Hz. Power meters show the import active power for standard types, or the import and export active power if the zero point is offset, i.e. in case of bidirectional energy directions.

# Measuring system and electronics

Core magnet moving-coil measuring system

Panel meters analog N+DIN-series - Power meters

- Integrated analog multiplier
- Linear scale characteristics
- Independent of waveform
- Independent of external fields

#### Design

Power meters are manufactured according to DIN 60 051 as well as according to the other relevant VDE and DIN regulations. The accuracy amounts to 1.5 % referred to the full scale.

The energy consumption lies at around 0.6 VA in the current path or at around 2 VA or 0.05 VA in the voltage path if a separate auxiliary voltage is used.

The full scale values should be adapted to the standard series 1/1.2/1.5/2/2.5/3/4/5/6/7.5/8 or a decadic multiple of these values. In case of reactive power meters for alternating current and four-wire three-phase current, the frequency range is restricted to a fixed value, normally 50 Hz. The auxiliary voltage for the supply of the electronics is gained from the measuring voltage. If the measuring voltage fluctuates by more than  $\pm$  20 % of the rated voltage, a separate auxiliary voltage is required.

In case of size 96, the electronic is installed in the housing (housing depth 57 mm). For all other sizes and models, a separate measuring transducer must be used. The output to the connection of the panel meter amounts to 0-20 mA. Further technical data of the measuring transducers are specified in the relevant data sheets (from page 24). The inputs are resistant to a permanent 1.2-fold overload, the current path withstands a temporary max. 20-fold overload. For the rest, DIN EN 60 051 applies. The electrical connection is done using clamping screws max. 4 mm<sup>2</sup>.

#### **Measuring ranges**

The full scale value may be selected between the 0,5-fold and 1,5-fold rated value of the apparent power.

Apparent power with alternating current  $S = U \times I$ 

with three-phase current  $S = U \times I \times \sqrt{3}$ 

(U = external conductor voltage)

#### **Special versions**

Measuring range zero point at any point of scale (bidirectional energy direction)

increased accuracy 1 %

Special calibration with active power fixed value between 100 Hz and 400 Hz

range between 40 Hz and 400 Hz range between 40 Hz and 1000 Hz


Special calibration with reactive power fixed value between 40 Hz and 400 Hz

except for 50 Hz (standard)

Auxiliary voltage  $\,$  separate auxiliary voltage 230 V or 110 V  $\pm$  20 % 45-65 Hz 2 VA

#### **Power meters**

Power meters - finding the right type



In case of these types (DWQ 96 ... DIN) electronics are installed in general (installation depth 57 mm). In connection with our power meter transducers (from page 27) all measuring instruments may be used for indicating the power.

Short legend	DWQ	Power meter for active power
	В	for reactive power
	96	Front frame 96 x 96 mm
	•••	without abbreviation, alternating current
	z	accessible neutral wire, 4-wire 3-phase current of same load
	nz	non-accessible neutral wire, 3-wire 3-phase current of same load
	d	double power meter, 3-wire 3-phase current of any load
	dr	triple power meter, 4-wire 3-phase current of any load
	DIN	built-in housing

 $\infty$ 



#### **Power meters**

electronic, for alternating and three-phase current, for use with current transformers secondary 1 A and 5 A

Type: **DWQ .. DIN** 

Square cut-out 40 - 100 Hz, class 1,5 Installation depth 57 mm Power consumption: current path 0,6 VA voltage path approx. 2 VA metal housing



Type	D 96 DIN	D 96 DIN	D 96 DIN	D 96 DIN	D 96 DIN
Front frame (mm)	96 x 96	96 x 96	96 x 96	96 x 96	96 x 96
Cut-out (mm)	92 x 92	92 x 92	92 x 92	92 x 92	92 x 92
Scale length (mm)	90	90	90	90	90
Weight (kg)	0,40	0,40	0,40	0,40	0,40
	Alternating	3-wire	3-wire	4-wire	4-wire
	current	3-phase	3-phase	3-phase	3-phase
		current	current	current	current
		same load	any load	same load	any load


## Types and variants

Rated voltage						
Active power		DWQ 96 DIN	DWQ 96 nz DIN	DWQ 96 d DIN	DWQ 96 z DIN	DWQ 96 dr DIN
V	100					
	230	х		_	_	_
	400	^	_	_	_	
	500					
	3 x 100					
	3 x 400	-	X	X	-	-
	3 x 500					
	100/58					
	400/230	-	-	-	X	X
	500/289					
Surcharge	10 A direkt	Х	X	X	Х	X
Reactive load		DWQB 96 DIN	DWQB 96 nz DIN	DWQB 96 d DIN	DWQB 96 z DIN	DWQB 96 dr DIN
V	100					
	230	X	-	-	-	-
	400					
	3 x 100					
	3 x 400	-	X	X	-	-
3 x 500 100/58 400/230	3 x 500					
	100/58					
	400/230	-	-	-	X	X
	500/289					
Surcharge	10 A direct	Х	Х	Х	Х	Х


In connection with measuring transducers type P ... - MU (from page 28), all measuring instruments may be used for power measurement. The advantage is that only two lines (20 mA) must be connected to the panel meter and that the measuring transducer may be mounted at a central location.




#### **Alternating current**




#### 3-wire 3-phase current same load




#### 4-wire 3-phase current same load



#### 3-wire 3-phase current any load



#### 4-wire 3-phase current any load





 $\infty$ 

## Power factor meters

Application	Power factor meters serve for measuring the ratio between active and apparent power in alterna-
	ting and three-phase current grids of 50 Hz, 60 Hz or 400 Hz sinusoidal.
Measuring system and	Core magnet moving-coil measuring system
electronics	<ul> <li>Zero point comparator of current and voltage</li> </ul>
	<ul> <li>Independent of external fields</li> </ul>
Design	Power factor meters are manufactured according to DIN 60 051 as well as according to the other
	relevant VDE and DIN regulations. The accuracy amounts to 1.5 % referred to the scale length. The
	energy consumption lies at around 0.6 VA in the current path or around 2 VA in the voltage path.
	The auxiliary voltage for the supply of the electronics is gained from the measuring voltage. The
	voltage range amounts to $\pm20\%$ of the rated voltage, the current range to $20\%$ to $120\%$ of the
	rated current. Exceeding these values may cause indication errors which are larger than the accu-
	racy rating. Currents $<$ 5 $\%$ of the rated value result in an uncontrolled indication. The inputs are
	resistant to a permanent 1.2-fold overload, the current path withstands a temporary max. 20-fold
	overload. DIN EN 60 051 applies.
	The electrical connection is done using clamping screws max. 4 mm <sup>2</sup>
Special versions	Measuring range deviating from standard measurement ranges
	Special calibration for 60 Hz or 400 Hz

Panel meters analog N+DIN-series - Power factor meters





## **Power factor meters**

electronic, for alternating and three-phase current


Type: **LWQ..DIN** 

Square cut-out 50 Hz, class 1,5			metal h	nousing	
Installation depth 57 mm For use with CT sec. 1 A or 5 A Power consumption current path 0,6 VA voltage path approx. 2 VA					
Туре	LWQ 72	2 DIN	LWQ 96 DIN	LWQ 72 nz DIN	LWQ 96 nz DIN
Front frame (mm)	72 x	72	96 x 96	72 x 72	96 x 96
Cut-out (mm)	68 x	68	92 x 92	68 x 68	92 x 92
Scale length (mm)	62	2	90	62	90
Weith (kg)	0,2	27	0,33	0,27	0,33
Measuring ranges	0,5 (	ا - cap 1	0,5 ind. or	0,5 cap 1	- 0,5 ind. or
	0,7	7 cap 1	I - 0,3 ind	0,7 cap	1 - 0,3 ind
	alt	ternatin	g current	3-phase	current


## Types and variants

Rated voltage				
100 V, 230 V, 400 V oder 500 V	Х	Х	-	-
3 x 100 V, 3 x 400 V, 3 x 500 V oder 3 x 690 V	-	-	X	X
Surcharge 10 A direct	Х	Х	Х	X

Connection for alternating current







Measuring transducers

Mains and limit

Energy meters

eters

rsanaseries 4 digita

Meas. instruments for Pa Pa C top hat rail mounting

7 Universal measuring instruments

S Current transformers

Shunts

Test apparatus

#### Frequency meters

Application	Frequency meters serve for measuring the mains frequency 50 Hz, 60 Hz, or 400 Hz. As measuring
	range just a selected partial range is used preferrably.
Measuring systems	Vibrating reed meter:
	Vibrating reed movement
	Pointer frequency meter:

- Core magnet moving-coil measuring system
- Integrated microcontroller
- Independent of waveform
- Large voltage range

Design Frequency meters are manufactured according to DIN EN 60 051 as well as according to the other relevant VDE and DIN regulations.

The accuracy amounts to 0.5 % referred to the full scale. The energy consumption lies between 1 VA and 4 VA depending on the reated voltage, measuring range and type. The measuring voltage may fluctuate between  $\pm$  20 % of the rated values without affecting the measured value indication. Pointer frequency meters offer two significant advantages over vibrating reed instruments:

- clear readability
- large voltage range, ± 20 % of rated voltage

The linear scale characteristic is perfectly linear and starts at 5% of the scale length above the mechanical zero point.

The temperature influence amounts to < 0.1 % with 10 K within a temperature range of - 25° to + 60 °C. The auxiliary voltage for the supply of the electronics is gained from the measuring voltage.

The current draw is approx. 10 mA. Pointer and vibrating reed meters are resistant to a 1.2-fold overload, temporarily up to a 2-fold overload, DIN EN 60 051 applies.

The connection is made using M4 screws (back-of-hand-proof).

## Special versions

Measuring voltage	Vibrating reed meters	400 V		
		500 V		
		600 V		
	Pointer frequency meters	between 12 V and 100 V		
		400 V		
		500 V		
		600 V		
Auxiliary voltage	Pointer frequency meters v	with separate auxiliary voltage for measuring voltages		
	0-100 %, 230 V or 110 V $\pm$ 15 % 45-65 Hz 2 VA (not for size 72)			
Measuring range	Pointer frequency meters o	ther than for standard measuring ranges e.g. 0-100 Hz		

 $\infty$ 

10 Test



## **Frequency meters**

Vibrating reed meters

Type: **F.. DIN** 

Square cut-out Vibrating reed movement Class 0,5 Energy consumption 1-4 VA Measuring voltage 100 V, 133 V, 230 V (please specify in order)



metal housing



Type	F 72 DIN	F 96 DIN	F 144 DIN
Front frame (mm)	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	138 x 138
Weight (kg)	0,20	0,30	0,70



## Types and variants

7 T					
Hz	Number of reeds	Subdivision in Hz			
45 - 50 - 55	13	1			
47 - 50 - 53	13	1/2	V	V	V
55 - 60 - 65	13	1	^	^	^
57 - 60 - 63	13	1/2			



## **Frequency meters**

Pointer frequency meters

Type: **FZQ .. DIN** 

Square cut-out
Moving-coil measuring system
Class 0,5 or 0,2
Energy consumption ca. 2 VA
Measuring voltage 100 V, 133 V, 230 V
(please specify in order)

motal	housing
metai	housing





Туре	FZQ 72 DIN	FZQ 96 DIN	FZQ 144 DIN
Front frame (mm)	72 x 72	96 x 96	144 x 144
Cut-out (mm)	68 x 68	92 x 92	138 x 138
Scale length	62	90	130
Weight (kg)	0,35	0,40	0,70



Hz	Measuring range	class			
50	45 - 50 - 55	0,5	132,70	132,70	161,10
50	48 - 50 - 52	0,2	144,30	144,30	172,70
60	55 - 60 - 65	0,5	132,70	132,70	161,10
60	58 - 60 - 62	0,2	144,30	144,30	172,70
400	360 - 400 - 440	0,5	132,70	132,70	161,10
400	380 - 400 - 420	0,2	144,30	144,30	172,70





## **Operating hour counter**

for alternating and direct current

SZ 72/96

Square cut-out

SZ 48

Type: SZ..DIN

plastic metal housing housing

Alternating current synchroneous motor 50 Hz

metal housing

plastic housing

	 Syntemoneous motor 30 m2		
Туре	SZ 48	SZ 72 DIN	SZ 96 DIN
Front frame (mm)	48 x 48	72 x 72	96 x 96
Cut-out (mm)	45 x 45	68 x 68	92 x 92
Weight (kg)	0,10	0,22	0,30
Counter range (hrs.)	99.999,99	99.999,99	99.999,99
Energy consumption	approx. 1 VA	approx. 2,5 VA	approx. 2,5 VA

## Types and variants

Operating voltage ± 15%			
230 V 50 Hz	X	X	X
400 V 50 Hz	X	X	X

Direct current Quartz-controlled **SZ 48 Gs** SZ 72 Gs DIN SZ 96 Gs DIN Type 48 x 48  $72 \times 72$ 96 x 96 45 x 45 68 x 68 92 x 92

#### Front frame (mm) Cut-out (mm) Weight (kg) 0,15 0,26 0,37 Counter range (hrs.) 99.999,99 99.999,99 99.999,99

Оре	erating voltage ± 15%	Current draw			
٧	12 - 80	mA 1,4 - 1,5	-	Х	Х
V	12 - 48	ca. 20 mW at 12 V	Χ	-	-



## Phase sequence indication

#### Type: **NDR**



## **Application**

Phase sequence indicator are used for determining and monitoring the rotating field (phase sequence) in electrical systems.

#### **Design and function**

The instruments comply with DIN EN 61557-7. Indication is made by LEDs:

green = right-hand rotating field

red = left-hand rotating field

Additionally, three further LEDs indicate whether all three phase voltages are present or which phase is missing.



#### Technical data

	Voltage range	3 x 220 V - 3 x	₹ 500 V
	Frequency range	15 Hz - 500 H	Iz
	Current draw	max. 5 mA pe	er phase
	Temperature range	-15 °C to + <u>20</u>	°C to +30 °C to +55 °C
	Switch-on time	100 %	
Dimensions	Туре	NDR 72	NDR 96
	Front frame (mm)	72 x 72	96 x 96
	Cut-out (mm)	68 x 68	92 x 92



## Types and var.

NDR



## **Fault annunciators**

96 x 96

#### Types:

SM8 und SM16




#### **Function**

The fault annunciatiors use 8 (SM8) or 16 (SM16) two-color LEDs as a display. The LEDs may light up green or red. During the function test, the LEDs light up orange. The LEDs are controlled via connection terminals on the rear of the instrument. The control can take place with direct or alternating voltage, depending on the version. The scale can be easily removed and labeled through an opening on the side. The scale can also be labeled in the manufacturer's plant. An auxiliary voltage is always required for the collective alarm option. In the case of a collective alarm with storage, the reset button must be pressed to cancel the alarm and reset the alarm relay; without saving, the alarm is triggered by resetting the LEDs to green.




#### Connection

SM8 and SM16 at 24 VDC



SM8 and SM16 at 24 VDC with collective alarm and memory





#### Technical data

Input	Activation	24 VDC (Option: 60 VAC, 60 VDC or 24 V AC)
	Rated input current	6 mA per LED and colour (Option AC: 4,5 mA per LED and colour)
	Test input DC	24 VDC / 95 mA (SM16: 190 mA)
	Test input AC (Option)	24 VAC / 73 mA (SM16: 145 mA)
	Overload permanent	max. 30 V
	Temperature range	-25 °C to +20 °C to +30 °C to +55 °C
	External magnetic field influence	no (to 400 A/m)
	Electrical connection	screw terminal max. 4 mm <sup>2</sup>
	Test voltage	2,2 kV between input and housing
		2,2 kV between input and relay contacts
	Caution!	The inputs are not galvanically isolated from each other!
Alarm	Relay contacts	1 changeover contact
	Switching capacity	max. 250 VAC, 1250 VA
Weight		230g



5		
	SM 8	
	SM 16	
	Surcharges:	Operating with 24 VAC
		Operating with 60 VAC or DC
		Collective alarm with memory (auxiliary voltage required)
		Collective alarm without memory (auxiliary voltage required)
		Collective alarm for red LEDs only, with memory (auxiliary voltage required)
		Collective alarm for red LEDs only, without memory (auxiliary voltage required)
		Scale printed SM8
		Scale printed SM16

**Notice** 

asuring
4 Mes
limit
ains and
Ž (
eters
nergy me
ب س
Imeters
Pane
-e
eters an
Panel m
L
nents for
instrum
Meas. instrun
Universal measu-
niversal
1
ırrent
ت ر
Current



/ monitoring

O top hat rail mounting 5 log N+DIN-series 4- digital

/ ring instruments

Notice	

10 Test apparatus

General description		Page 48
Moving-iron measuring instruments		
Alternating current and alternating voltage	WAS 45	Page 49
Moving-coil measuring instruments		
Direct current and direct voltage	PAS 45	Page 50
Voltmeter selector switch		
7 switching positions	SUAS 45/7	Page 49



## **General description**

#### **Application**

Snap-on measuring instruments are mainly used for measuring heavy-current quantities in distribution boards. They allow for snap-on fastening on top hat rails.

#### Measuring systems

- Moving-iron measuring system
- Moving-coil measuring system

#### Special features

- standard front dimensions, 45 x 45 mm
- slim design, 2.5 module widths
- quadrant scale, 43 mm scale length
- contact-proof connecting terminals

#### General specifications

Snap-on measuring instruments are manufactured according to DIN 60 051 as well as according to the other relevant VDE and DIN regulations. The following variables may be measured: Direct current, direct voltage, alternating current, alternating voltage, operating hours. The accuracy amounts to 1.5 % referred to the full scale. Standard-type moving-iron ammeters dispose of a 2-fold overload scale.

All measuring instruments are resistant to a permanent 1.2-fold overload, ammeters temporarily to a max. 10-fold overload, voltmeters to an up to 2-fold overload. For the rest, DIN EN 60 051 applies. The measuring elements are mounted in an shock-resistant housing from polycarbonate. The housing dimensions comply with DIN 43 880 for built-in equipment for electrical installations. Connection is made to touch-proof captive M5 screws, max. 10 mm<sup>2</sup>.

#### **Special versions**

Mounting on vertical top hat rail


Measuring range without overload range (moving-iron)


outside of the standard series

Scales red marking at arbitray position of scale

colored sector at arbitray position of scale

### **Dimensional drawing**





 $\infty$ 



# Moving-iron measuring instruments

for alternating current and alternating voltage

Type: WAS 45

Snap-on fastening on top hat rail, 40-100 Hz, class 1,5 Please explicitly specify direct current! Ammeters with 2-fold overload scale Energy consumption: ammeters 0,6-1,5 VA, voltmeters approx. 2,5 VA

Туре	WAS 45
Installation width (mm)	45 (2.5 module width)
Scale length (mm)	43
Weight (kg)	0,10



## Types and variants

Measuring ranges		
V	100 250 500	х
A	1 1,5 2,5 4 6 10 15	Х
	25	X
for use with current	transformer	
	sec. 5 A (0,6 VA) sec. 1 A (0,6 VA)	х





Snap-on fastening on top hat rail for switchover between three different votlages and three phases against neutral acc. to VDE 0660

Туре	SUAS 45/7
Operating voltage	max. 690 V
Operating current	max. 16 A
IP code	IP 54
Screw terminal	max. 4 mm
Installation width	52,5 mm
	(3 module widths)
Installation depth 45 mm	
	X

# Voltmeter selector switch

## Type: **SUAS 45/7**







# Moving-coil measuring instruments

for direct current and direct voltage

Type: PAS 45

Snap-on fastening on top hat rail, class 1,5

Type		PAS 45	
Installation width (mm)		45	(2.5 module widths)
Scale length (mm)		43	
Weight (kg)		0,10	

## €

Types and v			
Measuring range	es	R <sub>e</sub> / R <sub>i</sub> / Δ U	
mV	100	200 Ω / V	
	150	200 Ω / V	
	250	200 Ω / V	X
	400	1000 Ω / V	
	500	1000 Ω / V	
V	1	1000 Ω / V	
•	1,5	1000 Ω / V	
	2,5	1000 Ω / V	
	4	1000 Ω / V	
	6	1000 Ω / V	
	10	1000 Ω / V	
	15 25	1000 Ω / V	
	25	1000 Ω / V	X
	40	1000 Ω / V	
	60	1000 Ω / V	
	100	1000 Ω / V	
	150	1000 Ω / V	
	250	1000 Ω / V	
	400	1000 Ω / V	
	500	1000 Ω / V	
	600	1000 Ω / V	
mA	1	28,6 Ω	
	1,5	14,2 Ω	
	2,5	7,6 Ω	
	4	3,8 Ω	
	6	1,9 Ω	
	10	1,4 Ω	
	15	1,3 Ω	
	25	60 mV	X
	40	60 mV	
	60	60 mV	
	100	60 mV	
	150	60 mV	
	250	60 mV	
	400	60 mV	
	600	60 mV	
A	1		
^		60 mV	
	1,5	60 mV	
	2,5	60 mV	V
	4	60 mV	X
	6	60 mV	
	10	60 mV	
	15	60 mV	
	25	60 mV	
for use with shun			
mV	60	12 Ω	X
	suring transducer		
mA	0-20	1,2 Ω	X
	4-20	50 Ω	X
V	0-10	10 k Ω	X

Measuring

Mains and limi monitoring

Energy meters


el meters tal

Panel meters analog

 $\infty$ 

Notice	

## Precision and service are the measure of all things



Universal measuring instruments

Shunts

Test apparatus

MÜLLER Heldtrische Messgeröte 53









#### **MÜLLER + ZIEGLER GmbH**

Elektrische Messgeräte Industriestraße 23 91710 Gunzenhausen, Germany Phone:+49 9831 5004-0 Mo - Thu 7 - 12 / 13 - 16 H and Fr 7 - 12 H Fax: +49 9831 5004-20

Fax: +49 9831 5004-20 info@mueller-ziegler.de www.mueller-ziegler.de

A member company of: **LÜBERG Technologieholding GmbH**Marienstr. 20, 90402 Nürnberg
www. lueberg-technologie.de

